




# NTSB TRB Truck and Bus Update

Robert Molloy, PhD

Director, Office of Highway Safety

January 8, 2025



AVIATION • RAILROAD • TRANSIT • HIGHWAY • MARINE • PIPELINE • COMMERCIAL SPACE

# The NTSB Board




Jennifer Homendy  
Chair



Alvin Brown  
Vice Chair



Michael E. Graham  
Member




Thomas B. Chapman  
Member




J. Todd Inman  
Member

# Changing Our Approach to Highway Safety



# Ongoing NTSB Highway Investigations





# Pittsburgh Bridge Collapse

- January 28, 2022, about 6:37 a.m.
- Structural failure and collapse
- Fell into Frick Park
- Dark with light snow
- Transit bus & 4 passenger vehicles
- Fifth passenger vehicle drove off abutment
- All injured transported by 8:26 a.m.
- Precautionary evacuation but no fire or explosion
- Emergency response excluded



# Fern Hollow Bridge Design

- Opened in 1973
- 447-foot-long, 64-foot-wide
- Uncoated weathering steel (UWS) bridge
- Three-span bridge with a rigid K-frame superstructure design type
- 26 tons posted weight limit
- Speed limit was 35 mph



Source: National Steel Bridge Alliance



# Westbound Video Evidence







# Bridge Failure Location Evidence



# Stiffeners on Southwest Leg

2013



Source: NBIS Inspection Report for Forbes Avenue Over Fern Hollow and Nine Mile Run, CDM Smith, September 2013

2021



Source: NBIS Inspection Report for Forbes Avenue Over Fern Hollow and Nine Mile Run, Gannett Flemming, Inc., September 2021




# Clogged Drainage Inlets

2005



Source: NBIS Inspection Report for Forbes Avenue Over Fern Hollow and Nine Mile Run, Wilbur Smith Associates, September 2005

2011



Source: NBIS Inspection Report for Forbes Avenue Over Fern Hollow and Nine Mile Run, Wilbur Smith Associates, September 2011

2017



Source: NBIS Inspection Report for Forbes Avenue Over Fern Hollow and Nine Mile Run, CDM Smith, September 2017

2021



Source: NBIS Inspection Report for Forbes Avenue Over Fern Hollow and Nine Mile Run, Gannett Flemming Inc., September 2021



# What We Found: FCM Inspection Plans



Bridge legs were not properly identified as fracture-critical

Bridge legs did not consistently undergo an in-depth FCM inspection

Maintenance and repair recommendations for the bridge legs were not assigned appropriate priority codes

Repairing the bridge legs could have prevented the collapse

The correct identification of FCMs is crucial



Source: Fatigue and Fracture Bridge Inspection Plan for Forbes Avenue Over Fern Hollow and Nine Mile Run, CDM Smith, January 2016

# What We Found: Load Rating Deficiency

- The calculations and assumptions used in the 2014 load rating analysis overestimated the Fern Hollow Bridge's capacity
  - Wearing Surface Thickness
  - Load rating assumed an incorrect  $k$ -factor (Cross bracing not intact)
  - Distributed section loss length of the leg
- Had the correct calculations and assumptions been used, the bridge would have been closed



# Fern Hollow Probable Cause

1. The failure of the transverse tie plate on the southwest leg of the bridge, a fracture-critical member (nonredundant steel tension member), due to corrosion and section loss
2. Resulting from the City of Pittsburgh's failure to act on repeated maintenance and repair recommendations from inspection reports.
3. Contributing to the collapse were:
  1. the poor quality of inspections,
  2. the incomplete identification of the bridge's fracture-critical members (nonredundant steel tension members), and
  3. The incorrect load rating calculations for the bridge.
  4. Insufficient oversight by the Pennsylvania Department of Transportation of the City of Pittsburgh's bridge inspection program.




# Williamsburg Crash Investigation

- December 16, 2022, about 1:36 a.m.
- Interstate 64 in Virginia
- Truck traveling 65 mph ran into back of a party bus traveling 25 mph
- 3 bus occupants died, 9 sustained serious injuries, and 11 sustained minor injuries.
- The truck driver also sustained serious injuries




Source: Virginia State Police

# Collision Sequence




# Truck Driver's 72 Hour History





# Truck ELD



# Williamsburg Safety Issues

- Inadequate safety culture of the truck motor carrier
  - Poor oversight of hours of service
  - Failure to manage the risk of driver fatigue
  - Lack of driver monitoring
- Commercial vehicle collision avoidance systems
- Inadequate safety management and oversight of the bus carrier
  - Unlicensed driver
  - Maintenance deficiencies
  - Inadequate state oversight


# Louisville Crash Investigation

- January 28, 2023, about 6:00 a.m.
- LBFNY company bus Westbound SR-37
  - 2013 Chevrolet Express bus
  - ~53-54 mph
- Aero Global Logistics box truck Eastbound SR-37
  - 2021 Freightliner box truck
  - ~59 mph
- Roadway was wet, lane markings visible, light snow






# Crash Sequence



# Crash Sequence (Continued)





# Roadway Evidence






# Bus Intrusion and Integrity Loss




# Bus Injuries

- Restrained driver – minor injuries
- Restrained passenger – serious head trauma
- Six fatalities
- Three unbelted ejected
- Multiple unbelted bus passengers displaced from their seats



# Truck Driver's 72 Hour History





# Louisville Safety Issues

- Lack of seat belt use by the bus occupants
  - Access to belts
  - Use of belts
- Inadequate safety practices of the truck motor carrier (AGL)
  - Managing fatigue
  - Crash risk
- Deficient oversight of motor carrier operations by the FMCSA
  - Continuity of operations
  - Operating without authority

# AGL Roadside Data vs. Compliance Review

## February 2020


- SMS data = Moderate-Risk
- CR = Satisfactory safety rating


## April 2021

- SMS data = Moderate-Risk
- CR = Unrated

## June 2022

- SMS data = Risk
- CR = Satisfactory safety rating





“From tragedy  
we draw  
knowledge to  
improve the  
safety of us all.”



